

1Q 2002 Shutdown Worklist					
Item	Work Scope	Source	Justification/Background	Resolution	
62. 3, 4 and 7 sidecut piping inspection	Stage, strip and inspect piping	Inspection	Sulfidation mechanism in these systems	Add to list 5/11/01	